National Transportation Safety Board Washington, DC 20594

Brief of Accident

Adopted 12/06/2002

DI	ΕN	102	LA	06	0
					_

File No. 12514		06/19/2002	Telluride, CO	Aircraft Reg No. N9089H		Time (Local): 10:30 MDT	
Airo Numb Operating Type of Flig	e Make/Model: craft Damage: er of Engines: Certificate(s): ght Operation:	1 None		Crew Pass	Fatal 0 0	Serious 0 0	Minor/None 1 1
Airr Runway Runway Len Rui	Destination: port Proximity:	Telluride Regional Airport 9 6870 / 100 Asphalt			Weath Basi Lowe Wind Tempel		Veather Observation Facility lisual Conditions lone 0.00 SM 50 / 006 Kts 1
Pilot-in-Command Certificate(s)/Rating(s) Flight Instructor; Cor Instrument Ratings Airplane	Age: mmercial; Multi	20 -engine Land; Single-engine Land	d	т	Total Las Total M	me (Hours) All Aircraft: 2 st 90 Days: 2 ake/Model: 1 nent Time: U	9 9

The pilot reported he flew the final approach at too fast an airspeed. The pilot said, "As a result of this extra speed, I porpoised on landing." An examination of the airplane revealed damage to the firewall and a propeller blade. No other anomalies were revealed.

Brief of Accident (Continued)

DEN02LA060

File No. 12514 06/19/2002 Telluride, CO Aircraft Reg No. N9089H Time (Local): 10:30 MDT

Occurrence #1: HARD LANDING

Phase of Operation: LANDING - FLARE/TOUCHDOWN

Findings

1. (C) AIRCRAFT CONTROL - NOT MAINTAINED - PILOT IN COMMAND

- 2. (F) PORPOISE/PILOT-INDUCED OSCILLATION ENCOUNTERED PILOT IN COMMAND
- 3. (F) AIRSPEED HIGH
- 4. (F) REMEDIAL ACTION DELAYED PILOT IN COMMAND

Findings Legend: (C) = Cause, (F) = Factor

The National Transportation Safety Board determines the probable cause(s) of this accident as follows. the pilot not maintaining proper aircraft control resulting in a hard landing. Factors contributing to this accident were the high airspeed, the porpoise encountered during the landing, and the pilot's delayed remedial action resulting in the damage to the airplane.